



AIR TRANSPORT LOCALS

514-521-561-562-563-564-565

TRANSPORT WORKERS UNION OF AMERICA, AFL-CIO

“STANDING SHOULDER TO SHOULDER”

In the past two days our Company has experienced an event that has not occurred at American Airlines since 1979. The FAA has temporarily revoked American Airlines MD80 operating certificate (essentially grounding the fleet) until inspection and work is completed on ECO 3064.

The Line Maintenance Presidents strongly advise any members performing work on this ECO (MD80 auxiliary pump harness) to properly document all associated work for your personal record. This would include any conversations and/or directions given from the FAA and American Airlines. Having this information is vital should you receive a Letter of Investigation (LOI) from the FAA regarding any work performed.

Should you receive an LOI from the FAA, please contact your Local union representative.
